



海軍大氣海洋局航船布告

中華民國110年11月22日

216 (暫) 臺灣西部海域 — 燈浮故障

依據 交通部航港局中部航務中心110年11月9日中技字第1103255189A號函。
說明 編號E1、S2、W1、W2基點浮標故障，修復後另行公告，航經該水域船隻請注意安全。
位置 (1) 北緯 23°36'24.4"，東經 120°04'04.6" (E1)
(2) 北緯 23°31'43.6"，東經 120°02'29.4" (S2)
(3) 北緯 23°37'46.0"，東經 119°59'43.4" (W1)
(4) 北緯 23°34'41.3"，東經 119°59'04.7" (W2) (WGS84)
海圖 04507 - 0336

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Nov-22-2021

216 (T) Taiwan West Waters – Buoy Damaged

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1103255189A dated November 9, 2021.
Details #E1, #W1, #W2, #S2 cardinal buoys had stopped functioning, and a further notice will be issued while fixed. Mariners are advised to navigate with caution in the area.
Position (1) 23°36'24.4"N., 120°04'04.6"E. (E1)
(2) 23°31'43.6"N., 120°02'29.4"E. (S2)
(3) 23°37'46.0"N., 119°59'43.4"E. (W1)
(4) 23°34'41.3"N., 119°59'04.7"E. (W2) (WGS84)
Chart affected 04507 - 0336

CAPT. Yung-Da Sun
Commanding Officer, NMOO