



海軍大氣海洋局航船布告

中華民國114年11月6日

177 (暫) 苗栗外海 — 燈器故障及復光

依據 交通部航港局中部航務中心114年10月27日中安字第1143213056A號函。

說明 1. No. C14風機識別版照明燈故障，修復後另行通知。
2. No. A06風機識別版照明燈復光。
3. 航經該水域船隻請多加注意。

位置 1. 北緯 24°41'58.2"，東經 120°49'35.9" (C14)
2. 北緯 24°43'10.0"，東經 120°49'35.0" (A06) (WGS84)

關係圖書 0356 - 04510 - 04511

參考布告 114年第41(暫)號航船布告。

海軍大氣海洋局局長
海軍上校 林 倉 玉

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Nov-6-2025

177 (T) Miaoli Offshore – Lighting Failure and Fixed

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1143213056A dated October 27, 2025.

Details 1. No. C14 wind turbine ID board lighting stopped functioning. Further information will be issued while fixed.
2. No. A06 wind turbine ID board lighting resume normal operation.
3. Mariners are advised to navigate with caution in this area.

Position 1. 24°41'58.2"N., 120°49'35.9"E. (C14)
2. 24°43'10.0"N., 120°49'35.0"E. (A06) (WGS84)

Chart affected 0356 - 04510 - 04511

Reference Former Notice 41(T)/2025.

CAPT. Tsang Yu, Lin
Director, NMOO