



海軍大氣海洋局航船布告

中華民國115年9月8日

154 (暫) 高雄港第二港口 — 導燈暫停發光

依據 臺灣港務股份有限公司高雄港務分公司115年9月2日高港港字第1156592423號函。
說明 高雄港第二港口導燈暫停發光，修復後另行通知，航經該水域船隻請注意安全。
位置 1. 北緯22°32'37.4"，東經120°17'10.4"
2. 北緯22°33'13.5"，東經120°18'43.3" (WGS84)
關係圖書 0338 - 0340 - 0341B - 0341C - 04504
刊物 中華民國燈表(109年第12版，刊物第五種)，編號：31711, 31737

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Sep-8-2026

154 (T) Second Entrance of Kaohsiung Port – Leading Beacon Temporarily Stop Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1156592423 dated September 2, 2026.
Details Leading beacons, located in Second Entrance of Kaohsiung Port, temporarily stopped functioning. Further information will be issued while fixed. Mariners should navigate with caution in this area.
Position 1. 22°32'37.4"N., 120°17'10.4"E.
2. 22°33'13.5"N., 120°18'43.3"E. (WGS84)
Chart affected 0338 - 0340 - 0341B - 0341C - 04504
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), beacon No. 31711, 31737

CAPT. Te Huang, Liu
Director, NMOO