



海軍大氣海洋局航船布告

中華民國115年3月3日

37 (暫) 苗栗外海 — 燈器故障

依據 交通部航港局中部航務中心115年2月10日中安字第1153210491A號函。
說明 下列位置之風機警示燈故障，修復後將另行通知，航經該水域船隻請多加注意。
位置 1. 北緯 24°43'39.9"，東經 120°49'41.9" (A02)
2. 北緯 24°43'49.6"，東經 120°49'29.4" (A03)
3. 北緯 24°42'45.9"，東經 120°50'05.5" (A04)
4. 北緯 24°43'12.0"，東經 120°48'46.9" (B13)
5. 北緯 24°41'58.2"，東經 120°49'35.9" (C14)
6. 北緯 24°41'35.8"，東經 120°49'01.5" (D21)
7. 北緯 24°41'42.7"，東經 120°48'25.4" (D25)
8. 北緯 24°41'27.6"，東經 120°48'24.1" (D28) (WGS84)

關係圖書 0356 - 04510 - 04511

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Mar-3-2026

37 (T) Miaoli Offshore – Lighting Failure

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1153210491A dated February 10, 2026.

Details WTG warning lights at the following positions had stopped functioning due to the damage, and further notice will be issued while fixed. Mariners are advised to navigate with caution in this area.

Position 1. 24°43'39.9"N., 120°49'41.9"E. (A02)
2. 24°43'49.6"N., 120°49'29.4"E. (A03)
3. 24°42'45.9"N., 120°50'05.5"E. (A04)
4. 24°43'12.0"N., 120°48'46.9"E. (B13)
5. 24°41'58.2"N., 120°49'35.9"E. (C14)
6. 24°41'35.8"N., 120°49'01.5"E. (D21)
7. 24°41'42.7"N., 120°48'25.4"E. (D25)
8. 24°41'41.6"N., 120°48'24.1"E. (D28) (WGS84)

Chart affected 0356 - 04510 - 04511

CAPT. Te Huang, Liu
Director, NMOO