



海軍大氣海洋局航船布告

中華民國115年9月15日

156 彰化外海 — 新增風機

依據 經濟部115年9月8日經授能字第11500131730號函。
說明 下列參考布告之海龍二號離岸風場，新增六座風機，航經該水域船隻請注意避讓及禁止下錨。
位置 1. 北緯24°00'52.4"，東經119°53'18.5" (HL21-B01)
2. 北緯24°00'32.9"，東經119°53'56.8" (HL21-B02)
3. 北緯23°59'41.9"，東經119°53'17.4" (HL21-B03)
4. 北緯24°00'52.8"，東經119°52'52.8" (HL21-H01)
5. 北緯24°00'57.0"，東經119°52'12.3" (HL21-H02)
6. 北緯24°01'00.5"，東經119°51'23.0" (HL21-H03) (WGS84)
參考布告 115年第102、122及137號航船布告

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Sep-15-2026

156 Changhua Offshore – Wind Turbine Added

Source Ministry of Economic Affairs, letter No. 11500131730 dated September 8, 2026.
Details Six wind turbines have been deployed as reference in the former notice regarding the Hai Long 2 Offshore Wind Farm. Mariners are advised to navigate with caution in the area and anchoring is prohibited.
Position 1. 24°00'52.4"N., 119°53'18.5"E. (HL21-B01)
2. 24°00'32.9"N., 119°53'56.8"E. (HL21-B02)
3. 23°59'41.9"N., 119°53'17.4"E. (HL21-B03)
4. 24°00'52.8"N., 119°52'52.8"E. (HL21-H01)
5. 24°00'57.0"N., 119°52'12.3"E. (HL21-H02)
6. 24°01'00.5"N., 119°51'23.0"E. (HL21-H03) (WGS84)
Reference Former Notice 102, 122 & 137/2026.

CAPT. Te Huang, Liu
Director, NMOO