



海軍大氣海洋局航船布告

中華民國115年10月2日

165 高雄港第二港口 — 導燈恢復發光

依據 臺灣港務股份有限公司高雄港務分公司115年9月24日高港港字第1156592719號函。
說明 高雄港第二港口導燈恢復發光。
位置 1. 北緯22°32'37.4"，東經120°17'10.4"
2. 北緯22°33'13.5"，東經120°18'43.3" (WGS84)
關係圖書 0338 - 0340 - 0341B - 0341C - 04504
刊物 中華民國燈表(109年第12版, 刊物第五種), 編號：31711, 31737
參考布告 取消115年第154(暫)號航船布告。

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Oct-2-2026

165 Second Entrance of Kaohsiung Port – Leading Beacon Resume Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1156592719 dated September 24, 2026.
Details Leading beacons, located in Second Entrance of Kaohsiung Port, resume normal operation.
Position 1. 22°32'37.4"N., 120°17'10.4"E.
2. 22°33'13.5"N., 120°18'43.3"E. (WGS84)
Chart affected 0338 - 0340 - 0341B - 0341C - 04504
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), beacon No. 31711, 31737
Reference Former Notice 154(T) /2026 are cancelled.

CAPT. Te Huang, Liu
Director, NMOO