



海軍大氣海洋局航船布告

中華民國115年10月2日

166 (暫) 高雄港第一港口 — 導燈暫停發光

依據 臺灣港務股份有限公司高雄港務分公司115年9月24日高港港字第1156592720號函。
說明 高雄港第二港口導燈暫停發光，修復後另行通知，航經該水域船隻請注意安全。
位置 北緯22°37'03.8"，東經120°15'22.6" (WGS84)
關係圖書 0336 - 0338 - 0340 - 0341A - 0341C - 04504 - 04505
刊物 中華民國燈表(109年第12版，刊物第五種)，編號：31330

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Oct-2-2026

166 (T) First Entrance of Kaohsiung Port – Leading Beacon Temporarily Stop Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1156592720 dated September 24, 2026.
Details A leading beacon, located in First Entrance of Kaohsiung Port, temporarily stopped functioning. Further information will be issued while fixed. Mariners should navigate with caution in this area.
Position 22°37'03.8"N., 120°15'22.6"E. (WGS84)
Chart affected 0336 - 0338 - 0340 - 0341A - 0341C - 04504 - 04505
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), beacon No. 31330

CAPT. Te Huang, Liu
Director, NMOO