本件屬公開資訊
UNCLASSIFIED

海軍大氣海洋局航船布告

中華民國115年10月30日

183 海洋浮標資訊更新

依　　據　國立中山大學115年10月21日中心海科字第1152900176號函。

說　　明　海洋浮標資訊更新，航經該水域船隻請注意避讓。

位　　置　詳如附件。

關係圖書　0331 - 0336 - 0350 - 0352 - 0353 - 04513 - 04514 - 04515 - 04525 - 04529

參考布告　110年第119、126號及113年第123號航船布告

海軍大氣海洋局局長
海軍上校　劉 得 凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Oct-30-2026

183 Maritime Buoy Information Updated

Source　National Sun Yat-sen University, letter No.1152900176 dated October 21, 2026.

Details　Maritime buoys information is updated at the following positions. Mariners are advised to navigate with caution in this area.

Position　See attachment.

Chart affected　0331 - 0336 - 0350 - 0352 - 0353 - 04513 - 04514 - 04515 - 04525 - 04529


Reference　Former Notice 119, 126/2021 & 123/2024.

CAPT. Te Huang, Liu
Director, NMOO

附件
Attachment

NM 183

(A)浮標更換(Buoy Replaced)

項次 Item	名稱 Name	位置 Position (WGS84)		錨碇點移動半徑(公尺) Moving radius (meter)	海　圖 Chart affected	符　號 Symbol
		更新前 Before update	更新後 Updated			
1	潮境海域 Chaojing Waters	25°08'37.0"N 121°48'33.0"E	25°08'34.0"N 121°48'38.0"E	100	0352, 0353, 04513, 04514	
2	蜜月灣海域 Honeymoon Bay Waters	24°56'51.0"N 121°55'45.0"E	24°57'05.0"N 121°55'48.0"E		0350, 0352, 04514, 04515	
3	澎南海域 Penghunan Waters	23°30'27.6"N 119°37'18.6"E	23°30'24.0"N 119°37'19.0"E		0331, 0336, 04525, 04529	
4	大武崙海域 Dawulun Waters	25°10'26.3"N 121°42'53.2"E	25°10'18.0"N 121°42'55.0"E		0352, 0353, 04513	

說明(Note)：
浮標為裝有夜間警示燈及雷達反射器之黃色鋁合金浮體，直徑 2.5 公尺(含 AIS 虛擬標記)。
Aluminum alloy cone buoys are painted in yellow with warning light and radar reflector, and AIS AtoN, with a 2.5m diameter.

(B)浮標回收(Buoy Withdrawn)

項次 Item	名稱 Name	位置 Position (WGS84)	錨碇點移動半徑(公尺) Moving radius (meter)	海　圖 Chart affected	刪除符號 Deletion of Symbol
1	東吉嶼海域 Dongji Island Waters	23°14'23.0"N 119°39'27.0"E	100	0331, 0336, 04529	

說明(Note)：
浮標為裝有夜間警示燈及雷達反射器之黃色鋁合金浮體，直徑 2.5 公尺(含 AIS 虛擬標記)。
Aluminum alloy cone buoys are painted in yellow with warning light and radar reflector, and AIS AtoN, with a 2.5m diameter.