本件屬公開資訊
UNCLASSIFIED

海軍大氣海洋局航船布告

中華民國115年11月3日

187 (暫) 高雄二港口 — 導燈暫停發光

依　　據　臺灣港務股份有限公司高雄港務分公司115年10月28日高港港字第1156592974號函。

說　　明　高雄二港口導燈暫停發光，修復後另行通知，航經該水域船隻請注意安全。

位　　置　北緯22°33'00.9"，東經120°16'22.5"　(WGS84)

關係圖書　0338 - 0340 - 0341B - 0341C - 04504

刊　　物　中華民國燈表(109年第12版，刊物第五種)，編號：31701

海軍大氣海洋局局長
海軍上校　劉 得 凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Nov-3-2026

187 (T) Second Entrance of Kaohsiung Port – Leading Beacon Temporarily Stop Functioning

Source　Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1156592974 dated October 28, 2026.

Details　A leading beacon, located in Second Entrance of Kaohsiung Port, temporarily stopped functioning. Further information will be issued while fixed. Mariners should navigate with caution in this area.

Position　22°33'00.9"N., 120°16'22.5"E.　(WGS84)

Chart affected　0338 - 0340 - 0341B - 0341C - 04504

Publication affected　Pub. No.5 List of Lights (Edition 12th, 2020), beacon No. 31701

CAPT. Te Huang, Liu
Director, NMOO