海軍大氣海洋局航船布告

中華民國115年11月16日

196 (暫) 苗栗外海 — 航路標誌設施故障及恢復

依　　據　交通部航港局中部航務中心115年11月5日中安字第1153213311A號函。

說　　明　下列位置之風機航路標誌設施故障及恢復，修復後將另行通知，航經該水域船隻請多加注意。

位　　置　1. 故障：
(A01) 北緯 24°43'30.4"，東經 120°49'54.1"
(B17) 北緯 24°42'34.1"，東經 120°48'48.7"
(D31) 北緯 24°41'44.6"，東經 120°47'34.6"　(WGS84)

2. 恢復：
(C14) 北緯 24°41'58.2"，東經 120°49'35.9"　(WGS84)

關係圖書　0356 - 04510 - 04511

參考布告　115年第37(暫)及88號航船布告

海軍大氣海洋局局長
海軍上校　劉 得 鳳

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Nov-16-2026

196 (T) Miaoli Offshore – AtoN Failure and Restoration

Source　Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1153213311A dated November 5, 2026.

Details　The WTG AtoN at the following positions have experienced failure and restoration due to the damage, and further notice will be issued while fixed. Mariners are advised to navigate with caution in this area.

Position　1. Failure
(A01)24°43'30.4"N., 120°49'54.1"E.
(B17)24°42'34.1"N., 120°48'48.7"E.
(D31)24°41'44.6"N., 120°47'34.6"E.　(WGS84)

2. Restoration
(C14) 24°41'58.2"N., 120°49'35.9"E.　(WGS84)

Chart affected　0356 - 04510 - 04511

Reference　Former Notice 37(T) & 88/2026.

CAPT. Te Huang, Liu
Director, NMOO