



海軍大氣海洋局航船布告

中華民國112年10月20日

182 臺灣東部海域 — 海洋浮標重新佈放

依據 國家海洋研究院112年10月4日國研海科字第11200050762號函。
 說明 海洋浮標重新佈放，航經該水域船隻請注意避讓。
 位置 詳如附件。
 海圖 04514 - 04515 - 0350 - 0352
 參考布告 111年第128號航船布告。

海軍大氣海洋局局長
 海軍上校 林倉玉

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.



Oct-20-2023

182 Taiwan East Waters – Maritime Buoy Redeployed

Source National Academy of Marine Research, letter No. 11200050762 dated October 4, 2023.
 Details Maritime buoy had been redeployed. Mariners are advised to navigate with caution in this area.
 Position See attachment.
 Chart affected 04514 - 04515 - 0350 - 0352
 Reference Former Notice 128/2022.

CAPT. Tsang Yu, Lin
 Director, NMOO

附件
 Attachment

位置 Position (WGS84)		符號 Symbol
撤回 (Withdrawn)	24°57'03.0" N 121°55'33.0" E	 Fl.Y.4s Or
佈放 (Deployed)	24°56'49.0" N 121°55'39.0" E	AIS  Fl.Y.4s 氣象浮標

說明 (Note) :

- 浮標為裝有夜間警示燈及雷達反射器之黃色鋁合金錐形浮體(含AIS)，直徑2.5公尺，移動半徑100公尺。
- 燈質：黃閃光4秒。
- 1.Aluminum alloy cone buoy is painted in yellow with a warning light and radar reflector (including AIS AtoN), 2.5m diameter, moving radius about 100m.
- 2.Characteristic of light : Fl.Y.4s