



海軍大氣海洋局航船布告

中華民國114年2月5日

13 臺中港 — 燈浮移除及燈浮暫時移位

依據 交通部航港局中部航務中心114年1月17日中技字第1143250323A號函。
說明 為配合碼頭新建工程，下列位置(A)燈浮移除及位置(B)燈浮暫時移位，航經該水域船隻請注意避讓。
位置 (A) 移除
北緯24°15'41.5"，東經120°30'31.9" (WGS84)
(B) 暫時移位
自：北緯24°15'18.0"，東經120°30'21.7"
移至：北緯24°15'08.6"，東經120°30'18.3" (WGS84)
關係圖書 0357
刊物 中華民國燈表(109年第12版，刊物第五種)，編號：21360, 21380

海軍大氣海洋局局長
海軍上校 林 倉 玉

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Feb-5-2025

13 Taichung Port – Buoy Removed and Buoy Temporarily Displaced

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1143250323A dated January 17, 2025.
Details Due to wharf construction, position (A) buoy removed and position (B) buoy temporarily displaced. Mariners are advised to navigate with caution in the area.
Position (A) Buoy removed
24°15'41.5"N., 120°30'31.9"E. (WGS84)
(B) Buoy temporarily displaced
From: 24°15'18.0"N., 120°30'21.7"E.
To: 24°15'08.6"N., 120°30'18.3"E. (WGS84)
Chart affected 0357
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), buoy No. 21360, 21380

CAPT. Tsang Yu, Lin
Director, NMOO