



海軍大氣海洋局航船布告

中華民國114年4月28日

59 (暫) 臺灣西部海域 — 氣象浮標移位及水下麥克風移除

依據 交通部航港局中部航務中心114年4月14日中安字第1140002032A號函。

說明 1. 位置(A)氣象浮標移位，燈質修正為黃群閃光5(20)秒。
2. 位置(B)水下麥克風移除
3. 航經該水域船隻請注意避讓。

位置 (A)移位：
自：北緯23°37'32.0"，東經120°00'36.0"
移至：北緯23°37'29.6"，東經120°00'18.1" (WGS84)
(B)移除：
北緯 23°36'46.8"，東經 120°05'36.1" (WGS84)

關係圖書 0336 - 04507

參考布告 113年第83(暫)號航船布告

海軍大氣海洋局局長
海軍上校 林 倉 玉

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Apr-28-2025

59 (T) Taiwan West Waters – Weather Buoy moved and Hydrophone removed

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1140002032A dated April 14, 2025.

Details 1. Position (A) weather buoy had been moved. The characteristics is corrected to Fl(5).Y.20s.
2. Position (B) hydrophone had been removed.
3. Mariners are advised to navigate with caution in the area.

Position (A) Moved :
From: 23°37'32.0"N., 120°00'36.0"E. (WGS84)
To: 23°37'29.6"N., 120°00'18.1"E.
(B) Removed :
23°36'46.8"N., 120°05'36.1"E. (WGS84)

Chart affected 0336 - 04507

Reference Former Notice 83(T)/2024.

CAPT. Tsang Yu, Lin
Director, NMOO