

海軍大氣海洋局航船布告

第 12 號

臺灣海域

永安港 — 燈浮移位

- 參考布告 本局 105 年航船布告第 195 號。
- 位 置 (A) 北緯 22°49'16.0"，東經 120°11'41.7"。(WGS84)
(B) 北緯 22°49'08.5"，東經 120°11'29.8"。(WGS84)
(C) 北緯 22°49'18.1"，東經 120°11'44.7"。(WGS84)
(D) 北緯 22°49'12.0"，東經 120°11'23.6"。(WGS84)
- 說 明 為配合永安港浚挖作業，即日起至106年5月11日止，永安港航道2a及4號燈浮由原位置(A)及(B)移至新位置(C)及(D)；作業完成後，即移回原位置，航行船隻，注意避讓。
- 關係圖書 普通海圖第04505, 0338, 0336, 0340號。
本局燈表第十版(刊物第五種)第31230, 31240號。
- 根 據 台灣中油股份有限公司天然氣事業部永安液化天然氣廠
106年1月20日永安港務字第10610051090號函。
- 備 註 本局航船布告網址：<http://navy.mnd.gov.tw>

中華民國 106 年 2 月 6 日

海軍大氣海洋局局長
海軍上校 崔 怡 楓

NOTICE TO MARINERS

Published by Naval Meteorological &
Oceanographic Office, R.O.C.

No.12

Taiwan Waters

Yong-an LNG Harbor – Buoys Moved

- Reference* - NMOO Notice to Mariners No. 195 of 2016.
- Positions* - (A) Lat.22°49'16.0"N., Long.120°11'41.7"E. (WGS84)
(B) Lat.22°49'08.5"N., Long.120°11'29.8"E. (WGS84)
(C) Lat.22°49'18.1"N., Long.120°11'44.7"E. (WGS84)
(D) Lat.22°49'12.0"N., Long.120°11'23.6"E. (WGS84)
- Details* - Due to the dredging work, buoys No.2a and No.4 of Yong-an LNG harbor channel have been moved from the original position (A) and (B) to the new position (C) and (D) until May 11th, 2017. After dredging work is finished, buoys moved back to the original position. Mariners are advised to navigate with caution in the area.
- Chart affected* - NMOO Charts 04505, 0338, 0336, 0340.
NMOO Pub. No.5 List of Lights (Edition 10th), buoy no. 31230, 31240.
- Source* - CPC Corporation, Taiwan, letter No.10610051090 dated January 20th, 2017.
- Remarks* - Notice to Mariners Website: <http://navy.mnd.gov.tw>

CAPT I-Fong Tsui
Commanding Officer, NMOO
Zuoying, Taiwan,
Republic of China