

海軍大氣海洋局航船布告

第 5 號

臺灣海域

臺中港 — 導標恢復發光及維修

- 參考布告 本局 105 年航船布告第 119 號。
- 位 置 (A)北緯 24°17'41.5"，東經 120°29'54.0"。(WGS84)
(B)北緯 24°17'41.5"，東經 120°29'54.4"。(WGS84)
(C)北緯 24°16'46.6"，東經 120°31'51.0"。(WGS84)
(D)北緯 24°16'57.2"，東經 120°31'25.2"。(WGS84)
- 說 明 1. 上述位置(A), (B)及(C)之導標，已維修完畢，即日起恢復發光。
2. 上述位置(D)之導標，即日起進行維修作業暫停運作，修繕完畢後另行通知，航行該水域船隻，請注意安全。
- 關係圖書 普通海圖第 0357 號。
本局燈表第十版(刊物第五種)第20110, 20130, 20140, 20150號。
- 根 據 交通部航港局中部航務中心106年1月5日中技字第1063250017號函。
- 備 註 本局航船布告網址：<http://navy.mnd.gov.tw>

中華民國 106 年 1 月 12 日

海軍大氣海洋局局長
海軍上校 崔 怡 楓

NOTICE TO MARINERS

Published by Naval Meteorological &
Oceanographic Office, R.O.C.

No. 5

Taiwan Waters

Taichung Harbor –

Beacon Resume Functioning & Maintenance

- Reference* - NMOO Notice to Mariners No. 119 of 2016.
- Positions* - (A) Lat.24°17'41.5"N., Long.120°29'54.0"E. (WGS84)
(B) Lat.24°17'41.5"N., Long.120°29'54.4"E. (WGS84)
(C) Lat.24°16'46.6"N., Long.120°31'51.0"E. (WGS84)
(D) Lat.24°16'57.2"N., Long.120°31'25.2"E. (WGS84)
- Details* - 1. Three leading beacon at position (A), (B) and (C) had been resumed its normal function from this day.
2. The leading beacon maintenance work at the above positions (D) is now being undertaken from this day. During the period, the beacon will temporarily stop functioning and it will be issued a further notice after finished. Mariners are requested to proceed with caution when passing.
- Chart affected* - NMOO Chart 0357.
NMOO Pub. No.5 List of Lights (Edition 10th), beacon no. 20110, 20130, 20140, 20150.
- Source* - Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No.1063250017 dated January 5th, 2017.
- Remarks* - Notice to Mariners Website: <http://navy.mnd.gov.tw>

CAPT I-Fong Tsui
Commanding Officer, NMOO
Zuoying, Taiwan,
Republic of China