



海軍大氣海洋局航船布告

中華民國 106 年 7 月 25 日

63 (暫) 臺中港附近 — 鑽探作業

依據 交通部航港局中部航務中心106年7月18日中技字第1063252399號函。
說明 即日起至 106 年 9 月 17 日止，在下列各點進行海上地質鑽探作業，航經該水域船隻，請注意避讓。
位置 B1 北緯 24°14'35.0"，東經 120°27'55.7"。 B7 北緯 24°14'37.4"，東經 120°28'25.6"。
B2 北緯 24°15'08.4"，東經 120°28'08.7"。 B8 北緯 24°14'41.0"，東經 120°28'27.2"。
B3 北緯 24°15'41.9"，東經 120°28'21.7"。 B9 北緯 24°15'07.4"，東經 120°28'33.8"。
B4 北緯 24°16'07.6"，東經 120°28'26.4"。 B10 北緯 24°15'19.5"，東經 120°28'39.0"。
B5 北緯 24°14'30.1"，東經 120°28'22.5"。 B11 北緯 24°15'54.0"，東經 120°28'43.6"。
B6 北緯 24°14'33.7"，東經 120°28'24.1"。 B12 北緯 24°16'16.3"，東經 120°28'43.6"。
(WGS84)
海圖 60701 - 0357 - 04509 - 0356

海軍大氣海洋局局長
海軍上校 崔怡楓

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

July 25, 2017

63 (T) Approaches to Taichung Port – Drilling Operation

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1063252399 dated July 18, 2017.
Details Drilling operations are taking place at the following positions until September 17, 2017. Mariners are advised to navigate with caution in the area.
Position B1 24°14'35.0"N., 120°27'55.7"E. B7 24°14'37.4"N., 120°28'25.6"E.
B2 24°15'08.4"N., 120°28'08.7"E. B8 24°14'41.0"N., 120°28'27.2"E.
B3 24°15'41.9"N., 120°28'21.7"E. B9 24°15'07.4"N., 120°28'33.8"E.
B4 24°16'07.6"N., 120°28'26.4"E. B10 24°15'19.5"N., 120°28'39.0"E.
B5 24°14'30.1"N., 120°28'22.5"E. B11 24°15'54.0"N., 120°28'43.6"E.
B6 24°14'33.7"N., 120°28'24.1"E. B12 24°16'16.3"N., 120°28'43.6"E.
(WGS84)

Chart affected 60701 - 0357 - 04509 - 0356

CAPT. I-Fong Tsui
Commanding Officer, NMOO