



## 海軍大氣海洋局航船布告

中華民國107年8月29日

### 47 (暫) 東吉嶼燈塔暫停發光

依據 交通部航港局航安組107年8月24日第L10708003號航船布告。  
說明 1. 據報東吉嶼燈塔已暫停發光，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。  
2. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89786805)。  
位置 北緯23°15'36.8"，東經119°40'12.1" (WGS84)  
海圖 04529 - 0331 - 0336  
刊物 燈表 106年第十一版(刊物第五種), 51710

海軍大氣海洋局局長  
海軍上校 崔怡楓

### NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Aug-29-2018

### 47 (T) Dongji Islet Lighthouse Temporarily Stop Functioning

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners No. L10708003 dated August 24, 2018.  
Details 1. Dongji islet lighthouse is reported stopped functioning. It will be resumed without further notice. Mariners should navigate with caution in this area.  
2. Contact to the Maritime Safety Division (Tel:886-2-89786805) for the latest information.  
Position 23°15'36.8"N., 119°40'12.1"E. (WGS84)  
Chart affected 04529 - 0331 - 0336  
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), lighthouse No. 51710

*CAPT. I-Fong Tsui*  
*Commanding Officer, NMOO*