



## 海軍大氣海洋局航船布告

中華民國108年1月17日

### 3 (暫) 浮塹燈杆暫停發光

依據 交通部航港局航安組108年1月14日第L10801001號航船布告。  
說明 1. 據報浮塹燈杆已暫停發光，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。  
2. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89786805)。  
位置 北緯23°32'20.2"，東經119°31'28.7" (WGS84)  
海圖 0334 - 04525 - 04529 - 0331 - 0336  
刊物 燈表 106年第十一版(刊物第五種), 51350

海軍大氣海洋局局長  
海軍上校 孫永大

### NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Jan-17-2019

### 3 (T) Fuwen Beacon Temporarily Stop Functioning

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners No. L10801001 dated January 14, 2019.  
Details 1. It's reported that Fuwen beacon had stopped functioning. It will be resumed without further notice while fixed. Mariners should navigate with caution in this area.  
2. Contact to the Maritime Safety Division (Tel:886-2-89786805) for the latest information.  
Position 23°32'20.2"N., 119°31'28.7"E. (WGS84)  
Chart affected 0334 - 04525 - 04529 - 0331 - 0336  
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), lighthouse No. 51350

*CAPT. Yung-Da Sun*  
*Commanding Officer, NMOO*