



海軍大氣海洋局航船布告

中華民國109年2月6日

11 (暫) 臺中港 — 燈浮維修

依據 交通部航港局中部航務中心109年1月22日中技字第1093250223A號函。
說明 臺中港CD1及CD2柱燈浮，即日起進行維修作業暫停運作，修繕完畢後另行通知，航經該水域船隻，請注意安全。
位置 北緯 24°15'38.4"，東經 120°31'08.5"
北緯 24°15'39.2"，東經 120°31'05.8" (WGS84)
海圖 0357
刊物 燈表 106年第十一版(刊物第五種) 21300, 21310

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Feb-6-2020

11 (T) Taichung Port – Light-buoy Maintenance

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No.1093250223A dated January 22, 2020.
Details CD1 & CD2 light-buoys of Taichung Port temporarily stop functioning due to maintenance work, and a further notice will be issued while the maintenance work is done. Mariners are advised to navigate with caution in the area.
Position 24°15'38.4"N., 120°31'08.5"E.
24°15'39.2"N., 120°31'05.8"E. (WGS84)
Chart affected 0357
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), buoy No. 21300, 21310

CAPT. Yung-Da Sun
Commanding Officer, NMOO