



海軍大氣海洋局航船布告

中華民國109年12月9日

113 (暫) 臺灣西部海域 — 海上工程及燈浮資訊更新

依據 交通部航港局中部航務中心109年11月26日中技字第1093254279A號函。

- 說明
1. 離岸風電新建工程進行中，請詳閱附件。
 2. 編號E-1基點浮標復光及移位。
 3. 編號E-2、N-2、S-2基點浮標故障，修復後另行公告。
 4. 編號YUN53基樁佈放完成，頂部架設警示燈。
 5. 航經該水域船隻請注意避讓。

位置 詳如附件。

海圖 04507 - 0336

參考布告 109年第第43(暫)號附件(A)及第87(暫)號航船布告。

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Dec-9-2020

113 (T) Taiwan West Waters – Maritime Work and Buoy Information Updated

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1093254279A dated November 26, 2020.

- Details
1. Offshore wind power construction maritime work is being undertaken, see attachment.
 2. #E-1 cardinal buoy is fixed up and the location is amended.
 3. #E-2, #N-2, #S-2 cardinal buoys had stopped functioning, and a further notice will be issued while fixed.
 4. #YUN53 monopile has been installed with a warning light on the top.
 5. Mariners are advised to navigate with caution in the area.

Position See attachment.

Chart affected 04507 - 0336

Reference Former Notice 43(T) attachment (A) and 87(T)/2020.

CAPT. Yung-Da Sun
Commanding Officer, NMOO

(A) 海上工程 (Maritime Work) :

施工期程：即日起至 110 年 7 月 31 日 (Until July 31, 2021)

連接下列各點 (Joining the following points) :

點位 Point	WGS84	點位 Point	WGS84
1	23°39'26.0"N., 120°01'49.0"E.	8	23°31'16.0"N., 119°59'31.0"E.
2	23°39'28.0"N., 120°04'16.0"E.	9	23°31'54.0"N., 119°59'11.0"E.
3	23°38'34.0"N., 120°04'18.0"E.	10	23°33'15.0"N., 119°59'10.0"E.
4	23°34'09.0"N., 120°03'40.0"E.	11	23°36'54.0"N., 119°59'45.0"E.
5	23°33'16.0"N., 120°03'23.0"E.	12	23°37'46.0"N., 120°00'02.0"E.
6	23°31'51.0"N., 120°02'14.0"E.	13	23°39'26.0"N., 120°01'49.0"E.
7	23°31'39.0"N., 120°01'39.0"E.		

(B) 基點浮標 (Cardinal Buoys) :

編號 No.	燈名 Name	位置 Position (WGS84)	說明 Details
E-1	東方基點浮標 1 East cardinal buoy 1	23°36'24.0"N. 120°04'46.0"E.	1.恢復發光 (Normal functioning) 2.自 (Move from) : 23°36'22.1"N., 120°04'17.0"E. 移至 (To) : 23°36'24.0"N., 120°04'46.0"E.
E-2	東方基點浮標 2 East cardinal buoy 2	23°33'15.2"N. 120°03'40.9"E.	遺失 (Lost)
N-2	北方基點浮標 2 North cardinal buoy 2	23°39'42.2"N. 120°04'23.5"E.	燈光熄滅 (Extinguished)
S-2	南方基點浮標 2 South cardinal buoy 2	23°31'43.6"N. 120°02'29.4"E.	燈光熄滅 (Extinguished)

(C) 基樁 (Monopile) :

編號 No.	名稱 Name	位置 Position (WGS84)	說明 Details
YUN53	基樁 Monopile	23°34'12.4"N. 120°02'09.0"E.	頂部架設臨時警示燈 (Warning light is on the top) 燈質 (Characteristic) : Fl.Y.4s2M