



海軍大氣海洋局航船布告

中華民國110年7月26日

139 (暫) 臺灣西部海域 — 海上工程完工日期展延及燈浮資訊更新

依據 交通部航港局中部航務中心110年7月12日中技字第1103253000A號函。

說明 1. 離岸風電新建工程完工日期自110年7月31日展延至111年7月31日。
2. 編號N1、N2、E1、E2、S1、S2基點浮標復光。
3. 編號W1、W2基點浮標故障，修復後另行公告。
4. 航經該水域船隻請注意避讓。

位置 詳如附件。

海圖 04507 - 0336

參考布告 109年第43(暫)號附件(A)、87(暫)、113(暫)及129(暫)號航船布告。

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Jul-26-2021

139 (T) Taiwan West Waters – Completion of Maritime Work Postponed and Buoy Information Updated

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1103253000A dated July 12, 2021.

Details 1. The completed date of the maritime work is postponed from July 31, 2021 to July 31, 2022.
2. #N1, #N2, #E1, #E2, #S1, #S2 cardinal buoys resume normal operation.
3. #W1, #W2 cardinal buoys had stopped functioning, and a further notice will be issued while fixed.
4. Mariners are advised to navigate with caution in the area.

Position See attachment.

Chart affected 04507 - 0336

Reference Former Notice 43(T) attachment (A), 87(T), 113(T) and 129(T)/2020.

CAPT. Yung-Da Sun
Commanding Officer, NMOO

基點浮標 (Cardinal Buoys) :

編號 No.	燈名 Name	位置 Position (WGS84)	說明 Details
N1	北方基點浮標 1 North cardinal buoy 1	23°39'38.7" 120°01'45.8"	恢復發光 (Normal functioning)
N2	北方基點浮標 2 North cardinal buoy 2	23°39'42.2" 120°04'23.5"	
E1	東方基點浮標 1 East cardinal buoy 1	23°36' 24.4 " 120°04' 04.6 "	
E2	東方基點浮標 2 East cardinal buoy 2	23°33' 13.3 " 120°03' 50.5 "	
S1	南方基點浮標 1 South cardinal buoy 1	23°31'08.3" 119°58'58.4"	
S2	南方基點浮標 2 South cardinal buoy 2	23°31'43.6" 120°02'29.4"	
W1	西方基點浮標 1 West cardinal buoy 1	23°37'46.0" 119°59'43.4"	燈光熄滅 (Extinguished)
W2	西方基點浮標 2 West cardinal buoy 2	23°34'41.3" 119°59'04.7"	