



海軍大氣海洋局航船布告

中華民國110年10月13日

193 (暫) 高雄二港口 — 導燈暫停發光

依據 臺灣港務股份有限公司高雄港務分公司110年10月4日高港港行字第1103102349號函。
說明 1. 高雄二港口導燈暫停發光，修復後即照常發光，屆時不另公告，航行船隻請多加注意。
2. 欲知修復進度，請逕洽高雄港務分公司(電話：07-5711369 #105)。
位置 北緯22°33'10.6"，東經120°18'26.0" (WGS84)
海圖 0341B
刊物 中華民國燈表(109年第12版，刊物第五種)，編號：31729

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Oct-13-2021

193 (T) Second Entrance of Kaohsiung Port – Leading Beacon Temporarily Stop Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1103102349 dated October 4, 2021.
Details 1. A leading beacon, located in 2nd Entrance of Kaohsiung Port, temporarily stopped functioning. It will be resumed without further notice while fixed. Mariners should navigate with caution in this area.
2. Contact to the Port of Kaohsiung, TIPC. (Tel:886-7-5711369#105) for the latest information.
Position 22°33'10.6"N., 120°18'26.0"E. (WGS84)
Chart affected 0341B
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), beacon No. 31729

CAPT. Yung-Da Sun
Commanding Officer, NMOO