



海軍大氣海洋局航船布告


中華民國111年8月17日

125 (暫) 臺灣西部海域 — 燈浮資訊更新

依據 交通部航港局中部航務中心111年8月5日中技字第1110005875A號函。

說明 下列位置基點浮標更新為虛擬AIS自動識別標記。

位置 (1) 北緯23°39'38.7"，東經120°01'45.8" (N1)
(2) 北緯23°39'42.2"，東經120°04'23.5" (N2)
(3) 北緯23°36'24.4"，東經120°04'04.6" (E1)
(4) 北緯23°33'13.3"，東經120°03'50.5" (E2)
(5) 北緯23°31'08.3"，東經119°58'58.4" (S1)
(6) 北緯23°31'43.6"，東經120°02'29.4" (S2)
(7) 北緯23°37'46.0"，東經119°59'43.4" (W1)
(8) 北緯23°34'41.3"，東經119°59'04.7" (W2) (WGS84)

符號 加註  V-AIS

海圖 04507 - 0336

參考布告 109年第37(暫)號航船布告附件A.

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Aug-17-2022

125 (T) Taiwan West Waters – Buoy Information Updated

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No. 1110005875A dated August 5 2022.

Details Cardinal buoys at the following positions are updated to AIS AtoN.

Position (1) 23°39'38.7"N., 120°01'45.8"E. (N1)
(2) 23°39'42.2"N., 120°04'23.5"E. (N2)
(3) 23°36'24.4"N., 120°04'04.6"E. (E1)
(4) 23°33'13.3"N., 120°03'50.5"E. (E2)
(5) 23°31'08.3"N., 119°58'58.4"E. (S1)
(6) 23°31'43.6"N., 120°02'29.4"E. (S2)
(7) 23°37'46.0"N., 119°59'43.4"E. (W1)
(8) 23°34'41.3"N., 119°59'04.7"E. (W2) (WGS84)


Symbol Insert  V-AIS

Chart affected 04507 - 0336

Reference Former Notice 37(T)/2020 attachment A.

CAPT. Yung-Da Sun
Commanding Officer, NMOO