



海軍大氣海洋局航船布告

中華民國114年9月8日

148 臺灣海域 — 海洋浮標資訊更新

依據 財團法人成大研究發展基金會114年8月27日成大研基建字第1140001890號函。
說明 更新海洋浮標資訊。
位置 詳如附件。
海圖 0331 - 0336 - 0340 - 0343 - 0352 - 0353 - 0353A - 0354B - 0355 - 04501 - 04503 - 04507-
04512 - 04513 - 04514 - 04523 - 04525 - 04529
參考布告 112年第136號及113年第89、123號航船布告。

海軍大氣海洋局局長
海軍上校 林 倉 玉

NOTICE to MARINERS



Published by Naval Meteorological & Oceanographic Office, R.O.C.

Sep-8-2025

148 Taiwan Waters – Maritime Buoy Information Updated

Source NCKU Research & Development Foundation, letter No.1140001890 dated August 27, 2025.
Details Observation buoys information had been updated.
Position See attachment.
Chart affected 0331 - 0336 - 0340 - 0343 - 0352 - 0353 - 0353A - 0354B - 0355 - 04501 - 04503 -
04507- 04512 - 04513 - 04514 - 04523 - 04525 - 04529
Reference Former Notice 136/2023 & 89, 123/2023.

CAPT. Tsang Yu, Lin
Director, NMOO

項次 Item	位置 Position (WGS84)		錨碇點 移動半徑 (公尺) Moving radius (meter)	符 號 Symbol	海 圖 Chart affected
	撤回 (Withdrawn)	佈放 (Deployed)			
(A)交通部運輸研究所 (Institute of Transportation, MOTC)					
1	25°10'51.0"N 121°22'24.0"E	25°10'53.0"N 121°22'20.0"E	100		0352, 0354B, 0355, 04512, 04513
2	23°31'54.0"N 119°41'19.0"E	23°31'54.0"N 119°41'23.0"E			0331, 0336, 04525, 04529
3	-	25°09'55.0"N 121°45'48.0"E	120		0352, 0353, 0353A, 04513, 04514
(B)經濟部水利署第五河川分署 (Fifth River Management Branch, Water Resources Agency, MOEA)					
4	23°40'49.0"N 120°03'34.0"E	回收 (Withdrawn)	85		0336, 04507
5	21°54'59.0" N 120°48'39.0" E	21°54'58.0" N 120°48'40.0" E	50		0340, 0343, 304501, 04523
(C) 財團法人成大研究發展基金會 (NCKU Research & Development Foundation)					
6	-	22°16'11.0"N 120°15'00.0"E	600		0340, 04503

說明 (Note) :

浮標為裝有夜間警示燈及雷達反射器之黃色鋁合金浮體(含AIS虛擬標記)。

Aluminum alloy cone buoy (including AIS AtoN), painted in yellow with a warning light and radar reflector.