



海軍大氣海洋局航船布告

中華民國115年1月22日

12 (暫) 高雄二港口 — 導燈暫停發光

依據 臺灣港務股份有限公司高雄港務分公司115年1月14日高港港字第1156590125號函。
說明 高雄二港口導燈暫停發光，修復後另行通知，航經該水域船隻請注意安全。
位置 1. 北緯22°32'37.4"，東經120°17'10.4"
2. 北緯22°33'00.9"，東經120°16'22.5" (WGS84)
關係圖書 0338 - 0340 - 0341B - 0341C - 04504
刊物 中華民國燈表(109年第12版，刊物第五種)，編號：31711, 31701

局長海軍上校劉得鳳公出
政戰處長海軍中校任堅代行

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Jan-22-2026

12 (T) Second Entrance of Kaohsiung Port – Leading Beacon Temporarily Stop Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1156590125 dated January 14, 2026.
Details Leading beacons, located in Second Entrance of Kaohsiung Port, temporarily stopped functioning. Further information will be issued while fixed. Mariners should navigate with caution in this area.
Position 1. 22°32'37.4"N., 120°17'10.4"E.
2. 22°33'00.9"N., 120°16'22.5"E. (WGS84)
Chart affected 0338 - 0340 - 0341B - 0341C - 04504
Publication affected Pub. No.5 List of Lights (Edition 12th, 2020), beacon No. 31711, 31701

CDR. Chien Jen
for CAPT. Te-Huang Liu
Director, NMOO