



海軍大氣海洋局航船布告

中華民國115年8月28日

147 彰化外海 — 海纜位置更正

依據 內政部115年6月15日台內地字第1150023876號函。
海龍三號風電股份有限公司115年8月24日資訊。
說明 更正下列參考布告之海纜位置，航經該水域船隻禁止下錨。
位置 詳如附件。
關係圖書 0313 - 0319
參考布告 115年第109號航船布告

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Aug-28-2026

147 Changhua Offshore – Correction of Submarine Cable Position

Source Ministry of the Interior, letter No. 1150023876 dated June 15, 2026.
Information form Hai Long 3 Offshore Wind Power Co., Ltd, dated August 24, 2026.
Details Amend the position of submarine cables with reference to the former notice. Mariners are advised to navigate with caution in the area and anchoring is prohibited.
Position See attachment.
Chart affected 0313 - 0319
Reference Former Notice 109/2026.

CAPT. Te Huang, Liu
Director, NMOO

附件
Attachment

NM 147

連接下列各點(Joining the following points)：

點位 Point	WGS84	點位 Point	WGS84	點位 Point	WGS84
更正 115 年第 109 號航船布告：附件(E) M string – WB370 Amendment to Notice 109/2026: Attachment (E) M string – WB370					
1	24°01'25.9"N,119°46'20.1"E	17	24°01'14.9"N,119°46'17.3"E	33	24°00'38.9"N,119°46'48.2"E
2	24°01'19.7"N,119°46'16.9"E	18	24°01'06.6"N,119°46'23.2"E	34	24°00'38.7"N,119°46'48.5"E
3	24°01'19.4"N,119°46'16.8"E	19	24°01'06.3"N,119°46'23.5"E	35	24°00'38.4"N,119°46'48.9"E
4	24°01'19.1"N,119°46'16.6"E	20	24°01'01.4"N,119°46'27.5"E	36	24°00'38.2"N,119°46'49.3"E
5	24°01'18.8"N,119°46'16.5"E	21	24°01'01.1"N,119°46'27.7"E	37	24°00'37.9"N,119°46'49.6"E
6	24°01'18.4"N,119°46'16.5"E	22	24°00'48.1"N,119°46'37.7"E	38	24°00'31.1"N,119°47'03.0"E
7	24°01'18.1"N,119°46'16.4"E	23	24°00'47.8"N,119°46'38.0"E	39	24°00'30.9"N,119°47'03.4"E
8	24°01'17.8"N,119°46'16.4"E	24	24°00'47.5"N,119°46'38.3"E	40	24°00'30.7"N,119°47'03.8"E
9	24°01'17.4"N,119°46'16.4"E	25	24°00'47.2"N,119°46'38.6"E	41	24°00'30.5"N,119°47'04.1"E
10	24°01'17.1"N,119°46'16.4"E	26	24°00'46.9"N,119°46'38.9"E	42	24°00'30.2"N,119°47'04.4"E
11	24°01'16.8"N,119°46'16.5"E	27	24°00'46.7"N,119°46'39.3"E	43	24°00'29.9"N,119°47'04.7"E
12	24°01'16.4"N,119°46'16.5"E	28	24°00'44.6"N,119°46'42.3"E	44	24°00'29.6"N,119°47'05.0"E
13	24°01'16.1"N,119°46'16.6"E	29	24°00'44.3"N,119°46'42.7"E	45	24°00'23.1"N,119°47'10.9"E
14	24°01'15.8"N,119°46'16.8"E	30	24°00'44.0"N,119°46'43.0"E	46	24°00'22.2"N,119°47'11.8"E
15	24°01'15.5"N,119°46'16.9"E	31	24°00'43.8"N,119°46'43.3"E	47	24°00'21.2"N,119°47'12.7"E
16	24°01'15.2"N,119°46'17.1"E	32	24°00'39.2"N,119°46'47.9"E	48	24°00'09.6"N,119°47'25.0"E
更正 115 年第 109 號航船布告：附件(I) S string – WB310 Amendment to Notice 109/2026: Attachment (I) S string – WB310					
1	24°01'26.7"N,119°46'19.7"E	17	24°01'24.5"N,119°45'59.3"E	33	24°01'13.1"N,119°44'12.9"E
2	24°01'28.5"N,119°46'16.5"E	18	24°01'24.2"N,119°45'58.3"E	34	24°01'13.0"N,119°44'12.6"E
3	24°01'28.7"N,119°46'16.1"E	19	24°01'23.8"N,119°45'57.2"E	35	24°01'12.9"N,119°44'12.3"E
4	24°01'28.9"N,119°46'15.7"E	20	24°01'23.6"N,119°45'56.2"E	36	24°01'12.7"N,119°44'12.0"E
5	24°01'29.1"N,119°46'15.2"E	21	24°01'23.4"N,119°45'55.1"E	37	24°01'12.6"N,119°44'11.7"E
6	24°01'29.2"N,119°46'14.7"E	22	24°01'23.2"N,119°45'53.9"E	38	24°01'04.7"N,119°43'57.1"E
7	24°01'29.3"N,119°46'14.3"E	23	24°01'23.2"N,119°45'52.8"E	39	24°01'04.3"N,119°43'56.3"E
8	24°01'29.4"N,119°46'13.8"E	24	24°01'22.8"N,119°45'42.1"E	40	24°01'04.0"N,119°43'55.4"E
9	24°01'29.4"N,119°46'13.3"E	25	24°01'22.8"N,119°45'41.3"E	41	24°01'03.7"N,119°43'54.4"E
10	24°01'29.4"N,119°46'12.8"E	26	24°01'22.7"N,119°45'40.4"E	42	24°01'03.4"N,119°43'53.5"E
11	24°01'29.4"N,119°46'12.3"E	27	24°01'22.6"N,119°45'39.6"E	43	24°01'03.2"N,119°43'52.5"E
12	24°01'29.4"N,119°46'11.9"E	28	24°01'20.7"N,119°45'28.3"E	44	24°01'03.1"N,119°43'51.6"E
13	24°01'29.3"N,119°46'11.4"E	29	24°01'20.5"N,119°45'27.1"E	45	24°01'03.0"N,119°43'50.6"E
14	24°01'29.2"N,119°46'10.9"E	30	24°01'13.2"N,119°44'13.8"E	46	24°01'02.5"N,119°43'41.2"E
15	24°01'29.0"N,119°46'10.5"E	31	24°01'13.2"N,119°44'13.5"E		
16	24°01'28.9"N,119°46'10.0"E	32	24°01'13.1"N,119°44'13.2"E		