



海軍大氣海洋局航船布告

中華民國115年2月26日

30 (暫) 高雄第二港口 — 臨時燈杆設置

依據 臺灣港務股份有限公司高雄港務分公司115年2月10日高港港字第1156590365號函。
說明 高雄港第二港口導燈損壞不亮，在原位置設臨時助導航輔助燈，航經該水域船隻請注意安全。
位置 詳如附件。
關係圖書 0338 - 0340 - 0341B - 0341C - 04504
參考布告 115年第12(暫)號航船布告

海軍大氣海洋局局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Feb-26-2026

30 (T) Second Entrance of Kaohsiung Port – Temporary Beacon Deployed

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1156590365 dated February 10, 2026.
Details Leading beacons, located in Second Entrance of Kaohsiung Port, temporarily stopped functioning due to damage. Temporary beacons have been deployed at the same position. Mariners should navigate with caution in this area.
Position See attachment.
Chart affected 0338 - 0340 - 0341B - 0341C - 04504
Reference Former Notice 12(T)/2026.

CAPT. Te Huang, Liu
Director, NMOO

附件
Attachment

NM 30

點位 Point	位置 Position (WGS84)	燈質 Characteristics	見距 Range (mile)	符號 Symbol
1	22°32'37.4"N 120°17'10.4"E	紅閃光6秒 (明1.5秒，暗4.5秒) Fl.R.6s (1.5sL & 4.5sD)	5	 Fl.R.6s
2	22°33'00.9"N 120°16'22.5"E	綠閃光6秒 (明1.5秒，暗4.5秒) Fl.G.6s (1.5sL & 4.5sD)	5	 Fl.G.6s