



海軍大氣海洋局航船布告

中華民國108年9月18日

43 (暫) 金門-泉州航道燈浮燈光熄滅

依據 交通部航港局航安組108年9月4日航船布告。
說明 1. 據報金門-泉州航道C2及C4燈浮因燈器故障熄滅，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。
2. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89786805)。
位置 北緯24°30'07.9"，東經118°18'20.9"
北緯24°30'21.7"，東經118°22'09.8" (WGS84)
海圖 04526 - 0319A
刊物 燈表 106年第十一版(刊物第五種), 52160、52180

海軍大氣海洋局局長
海軍上校 孫永大

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Sep-18-2019

43 (T) Kinmen-Quanzhou Channel Light-buoy Extinguished

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners dated September 4, 2019.
Details 1. It's reported that the Kinmen-Quanzhou channel C2 & C4 light-buoys had extinguished due to the damage. It will be resumed without further notice while fixed. Mariners should navigate with caution in this area.
2. Contact to the Maritime Safety Division (Tel:886-2-89786805) for the latest information.
Position 24°30'07.9"N., 118°18'20.9"E.
24°30'21.7"N., 118°22'09.8"E. (WGS84)
Chart affected 04526 - 0319A
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), Buoy No. 52160, 52180

CAPT. Yung-Da Sun
Commanding Officer, NMOO