



海軍大氣海洋局航船布告


中華民國112年7月26日

130 (暫) 高雄二港口 — 臨時燈杆設置

依據 臺灣港務股份有限公司高雄港務分公司112年7月19日高港港字第1126592139號函。

說明 1.高雄二港口導燈損壞不亮，在原位置設一臨時助導航輔助燈，航經該水域船隻請注意安全。
2.臨時燈杆相關資料如下：
(1)燈質：紅閃光4秒 (明0.5秒，暗3.5秒)
(2)見距：2浬
(3)構造及高度：灰色圓柱(金屬)，3公尺

位置 北緯22°33'04.8"，東經120°19'00.6" (WGS84)

符號 加註  *Fl.R.4s2M*

海圖 0341B

參考布告 112年第123(暫)號航船布告

海軍大氣海洋局副局長
海軍上校 劉得凰

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Jul-26-2023

130 (T) Second Entrance of Kaohsiung Port – Temporary Beacon Deployed

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1126592139 dated July 19, 2023.

Details 1. A leading beacon, located in 2nd Entrance of Kaohsiung Port, temporarily stopped functioning due to damaged. Temporary beacon has been deployed at the same place. Mariners should navigate with caution in this area.
2. The information about temporary beacon is as follows :
(1) Characteristics: Fl.R.4s (0.5sL , 3.5sD)
(2) Range: 2 nautical miles
(3) Structure & Height: Gray metal post ; 3 meters

Position 22°33'04.8"N., 120°19'00.6"E. (WGS84)

Symbol Insert  *Fl.R.4s2M*

Chart affected 0341B

Reference Former Notice 123(T)/2023.

CAPT. Te-Huang Liu
Deputy Director, NMOO