



海軍大氣海洋局航船布告

中華民國107年11月12日

65 (暫) 花蓮港燈塔暫停發光

依據 交通部航港局航安組107年11月6日第L10711006號航船布告。

說明 1. 據報花蓮港燈塔已暫停發光，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。
2. 施工時間：即日起至107年11月28日。
3. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89786805)。

位置 北緯23°58'29.0"，東經121°36'48.7" (WGS84)

海圖 0351 - 04518 - 0348 - 0350

刊物 燈表 106年第十一版(刊物第五種), 41050

海軍大氣海洋局局長
海軍上校 崔怡楓

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Nov-12-2018

65 (T) Hualien Port Lighthouse Temporarily Stop Functioning

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners No. L10711006 dated November 6, 2018.

Details 1. It's reported that Hualien port lighthouse had stopped functioning for construction. It will be resumed without further notice while fixed. Mariners should navigate with caution in this area.
2. Construction period : Until November 28, 2018.
3. Contact to the Maritime Safety Division (Tel:886-2-89786805) for the latest information.

Position 23°58'29.0"N., 121°36'48.7"E. (WGS84)

Chart affected 0351 - 04518 - 0348 - 0350

Publication affected Pub. No.5 List of Lights (Edition 11, 2017), lighthouse No. 41050

CAPT. I-Fong Tsui
Commanding Officer, NMOO