



## 海軍大氣海洋局航船布告

中華民國109年2月4日

### 10 (暫) 蘇澳港南防波堤燈杆暫停發光

依據 交通部航港局航安組109年1月20日第3(初)號航船布告。  
說明 1. 據報蘇澳港南防波堤燈杆已暫停發光，修復後即照常發光，屆時不另公告，航行船隻，請多加注意。  
2. 欲知修復進度，請逕洽交通部航港局航安組(電話：02-89786807)。  
位置 北緯 24°35'35.2"，東經 121°52'50.9" (WGS84)  
海圖 0351A - 04515 - 04516  
刊物 燈表 106年第十一版(刊物第五種), 42140

海軍大氣海洋局局長  
海軍上校 孫永大

### NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Feb-4-2020

### 10 (T) Su'ao Port S. Breakwater Beacon Temporarily Stop Functioning

Source Maritime Safety Division of the Maritime and Port Bureau, MOTC, notice to mariners No. 3(P) dated January 20, 2020.  
Details 1. It's reported that Su'ao port S. breakwater beacon had stopped functioning. It will be resumed without further notice while fixed. Mariners should navigate with caution in this area.  
2. Contact to the Maritime Safety Division ([Tel:886-2-8978 6807](tel:886-2-89786807)) for the latest information.  
Position 24°35'35.2"N., 121°52'50.9"E. (WGS84)  
Chart affected 0351A - 04515 - 04516  
Publication affected Pub. No.5 List of Lights (Edition 11, 2017), beacon No. 42140

*CAPT. Yung-Da Sun*  
*Commanding Officer, NMOO*