



## 海軍大氣海洋局航船布告

中華民國110年4月9日

### 52 (暫) 高雄港 — 導燈暫停發光

依據 臺灣港務股份有限公司高雄港務分公司110年4月1日高港港行字第1103101380號函。  
說明 1. 高雄港二座導燈暫停發光，修復後另行通知，航經該水域船隻請注意安全。  
2. 欲知修復進度，請逕洽高雄港務分公司(電話：07-5711369#109)。  
位置 (1) 北緯22°33'17.1"，東經120°19'46.2"  
(2) 北緯22°33'20.2"，東經120°20'03.4" (WGS84)  
海圖 0341B - 0341C - 04504  
刊物 中華民國燈表(109年第12版, 刊物第五種), 編號：31860、31870

海軍大氣海洋局局長  
海軍上校 孫永大

## NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Apr-9-2021

### 52 (T) Kaohsiung Port – Leading Beacon Temporarily Stop Functioning

Source Port of Kaohsiung, Taiwan International Ports Corporation Ltd., letter No. 1103101380 dated April 1, 2021.  
Details 1. Two leading beacons, located in Kaohsiung port, temporarily stopped functioning. Further information will be issued while fixed. Mariners should navigate with caution in this area.  
2. Contact to Port of Kaohsiung, TIPC. (Tel:886-7-5711369#109) for the latest information.  
Position (1) 22°33'17.1"N., 120°19'46.2"E.  
(2) 22°33'20.2"N., 120°20'03.4"E. (WGS84)  
Chart affected 0341B - 0341C - 04504  
Publication affected Pub. No.5 List of Lights (Edition 12, 2020), No. 31860, 31870

*CAPT. Yung-Da Sun*  
*Commanding Officer, NMOO*