



## 海軍大氣海洋局航船布告

中華民國111年6月2日

### 80 (暫) 麥寮港 — 燈標更新工程

依據 交通部航港局中部航務中心111年5月20日中技字第1113252680A號函。  
說明 麥寮港進港導航疊標，即日起至111年6月13日進行更新工程，完工後另行通知，航經該水域船隻請注意安全。  
位置 北緯 23°47'58.4"，東經 120°11'08.3"  
北緯 23°48'01.5"，東經 120°11'13.1" (WGS84)  
海圖 0361A - 0361 - 04508  
刊物 中華民國燈表(109年第12版, 刊物第五種), 編號：23010、23020

海軍大氣海洋局局長  
海軍上校 孫永大

### NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

June-2-2022

### 80 (T) Mailiao Port – Light Beacon Overhauling

Source Central Taiwan Maritime Affairs Center, Maritime and Port Bureau, MOTC, letter No.1113252680A dated May 20, 2022.  
Details The leading lights located in the Mailiao Port were overhauling until June 13, 2022, and a further notice will be issued while the overhauling is done. Mariners are advised to navigate with caution in the area.  
Position 23°47'58.4"N., 120°11'08.3"E.  
23°48'01.5"N., 120°11'13.1"E. (WGS84)  
Chart affected 0361A - 0361 - 04508  
Publication affected Pub. No.5 List of Lights (Edition 12<sup>th</sup>, 2020), beacon No. 23010, 23020

*CAPT. Yung-Da Sun*  
*Commanding Officer, NMOO*