



海軍大氣海洋局航船布告

中華民國114年9月18日

157 船及沉箱沉沒

依據 交通部航港局114年9月13日第20250520號礙航公告。

說明 1. 114年9月13日0630時，沉箱(尺寸25x20x15公尺)在下列位置(A)沉沒(水深80公尺)。
2. 114年9月13日0715時，浮沉台船在下列位置(B)沉沒(水深72公尺)。
3. 航行船隻請多加注意。

位置 (A) 北緯 24°57'07.3"，東經 121°59'20.6"
(B) 北緯 24°57'23.9"，東經 121°58'09.7" (WGS84)

符號 加註 (A) 
(B) 

關係圖書 0313 - 0350 - 0352 - 0360 - 04514 - 04515

海軍大氣海洋局局長
海軍上校 林 倉 玉

NOTICE to MARINERS

Published by Naval Meteorological & Oceanographic Office, R.O.C.

Sep-18-2025

157 Ship and Caisson Sank

Source Maritime and Port Bureau, MOTC, notice to mariners No. 20250520 dated September 13, 2025.

Details 1. A Caisson, size 25x20x15m, depth 80m, sank at the following position (A), on September 13, 2025.
2. A submersible heavy ship, depth 72m, sank at the following position (B) on September 13, 2025.
3. Mariners are advised to navigate with caution in this area.

Position (A) 24°57'07.3"N., 121°59'20.6"E.
(B) 24°57'23.9"N., 121°58'09.7"E. (WGS84)

Symbol Insert (A) 
(B) 

Chart affected 0313 - 0350 - 0352 - 0360 - 04514 - 04515

CAPT. Tsang Yu, Lin
Director, NMOO